
Rectangular Tubing Sign Display - Triple

Product Parts

- 1 Base
- 2 Lower Frame
- 3 Upper Frame (x2)
- 4 Hex Wrench
- 5 Screw (x8)





Display Set-Up

Step 1


Begin by removing all parts from the box and place on a clean, flat surface.

With the Base (1) placed on the floor with the Support Legs facing upwards, slide the Support Holes of the Lower Frame (2) over the Support Legs of the Base (1).



Step 2

Make sure the Lower Frame is in the upright position with the Graphic Insert visible on the bottom edge and not on the top edge.




Step 2

Using the Hex Wrench (4), insert and tighten two Screws (5) on each side.



Step 3

Slide the Support Legs of the Upper Middle Frame (3) into the the Support Holes on the top of the Lower Frame (2).



Step 4

Fasten in place using the Hex Wrench (4) and one Screw (5) on each side.

Repeat Steps 3 and 4 for the Upper Top Frame (3), placing it on top of the Upper Middle Frame (3).



Step 5

Lift up on the bottom of the Graphic Insert, pull back, and allow the frame to gently slide downwards until it catches. Tilt the Graphic Insert to an angle that makes it easiest to insert the Graphic into the Slit on the top. Lift the Graphic Insert and place it back within the Frame so that the notches catch within the grooves.







Storage & Care

Place all product parts into shipping box and store in a cool, dry location.

To clean, wipe with damp cloth.